Thank you for purchasing this Dynojet kit. This kit has been developed for a motorcycle which is set to the parameters listed at the right in the "Stage" description. If your motorcycle does not meet any of these parameters please check with Dynojet before installation. For technical assistance contact your Dynojet distributor or call Dynojet U.S.A. (800)-992-4993

> 2191 Mendenhall Dr. Suite 105 North Las Vegas, NV 89031 TEL: 702-399-1423 FAX: 702-399-1431 8am-5pm Pacific Time Monday through Friday

> > Website Address http://www.dynojet.com

The manufacturer and seller make no warranties express or implied which extend beyond the description of the goods contained herein. Any description of this product is for the purpose of identifying it and shall not be deemed to create an express warranty.




### E1145.003

**European Models Only** 

### 1994-98 Honda VT600 Shadow

Stage 1

For mildly tuned machines using the stock airbox, with stock or K&N filter. May also be used with a good aftermarket exhaust system K&N Filter #N/A



# WARNING

NO SMOKING! NO OPEN FLAME! WHILE INSTALLING YOUR JET KIT

Parts List		
2	Main Jet	DJ108
2	Main Jet	DJ112
2	Main Jet	DJ116
2	Fuel Needle	DNO114
2	Adjusting Washer	DW0001
2	E-clips	DE0001
1	Slide Drill	DD #40

#### STAGE ONE INSTRUCTIONS

1. Remove the vacuum slides from the carbs. Remove stock needles and spacers, noting order of assembly (Fig. A). Using drill bit provided (DD #40) enlarge your slide lift holes. The picture may not show your slide exactly. Drill only the stock slide lift holes, **do not drill the needle hole or any new holes.** 

2. Install the Dynojet needles on groove #2 from the top. Use all stock spacers (Fig. A). Install the small K&N washers above the E-clip. After installing the slides in the carbs be sure to check slide movement manually.

3. Remove the stock main jet and replace with Dynojet main jets provided. If you are running the stock exhaust use the DJ108 main jets. If you are using an aftermarket exhaust or slip-on with a high flow baffle use the DJ112 main jets. Be sure that the jets you are changing are the main jets.

4. Locate the fuel mixture plug (Fig. B). Carefully turn the mixture screws clockwise until lightly seated, then back out 11/2 turns.

## E1145.003

